



Technical Service Information

MAZDA G4A-EL BIND UP IN REVERSE

COMPLAINT: Bind up in Reverse.

CAUSE: Dished Plates installed incorrectly.

CORRECTION: Install dished plates as shown below.




Figure 1

FORWARD CLUTCH




Figure 2

COAST CLUTCH




Figure 3