



# Technical Service Information

## FORD ATX HARSH 2-3 UPSHIFT

### COMPLAINT:

Soft 1-2 shift  
Harsh 1-2 shift

**CAUSE:** 1-2 capacity modulator valve spring calibration

### CORRECTION:

Replace 1-2 capacity modulator valve spring with stronger spring.  
Replace 1-2 capacity modulator valve spring with weaker spring.




Figure 1