



Technical Service Information

NISSAN RL4F02A FALLS OUT OF OVERDRIVE AT TIMES

- COMPLAINT:** Transaxle upshifts ok, but downshifts 4-3 or 4-2 at highway speeds when you lift your foot off of the gas pedal.
- CAUSE:** The problem can be excessive end play in the governor shaft. This will cause the shaft to move upward on the spiral gear when coasting, and block governor feed oil.
- CORRECTION:** Remove the bolt and pin that holds the governor shaft into the case. Inspect the pin for wear and replace it if necessary. See figure 1




Figure 1