



Technical Service Information

NISSAN E/L4N71B BELLHOUSING LEAK

COMPLAINT: Oil leaking out of bell housing.

CAUSE: Bell housing to case bolts not sealed.

CORRECTION: All bell housing to case bolts MUST be installed with thread sealant. (See diagram below)




Figure 1