



Technical Service Information

THM 3T40 (125C) GASKET CHANGE

NOTE: GASKETS DO NOT RETROFIT, MIS-MATCH OF GASKETS CAN CAUSE NO TCC APPLY OR NO TCC RELEASE.




Figure 1