

5. Tighten the shield terminal with approximately 0.5 Nm.  
When doing this, ensure that the terminal is completely in contact with the exposed protective braided shield.




Figure 8-6 Mounting the shield contact