



Maintenance Job Card

Requested By: John Doe

Date Requested: 2026-01-10

Asset Description: Band Saw

Location: Maitland

Actioned By: Jane Doe

Date Actioned: 2026-02-05

Root Cause: environmental factors

Status: completed

Job Description

Water damage to the mincer. Requires urgent replacement of internal wiring.

Parts Used

Part Name	Quantity	Price (R)
Wiring Kit	1	R 3,000.00
Fuse 15A	2	R 91.90

Subtotal : R 3,091.90

Labour & Travel Costs

Service	Qty	Price (R)
Travel (Kilometers)	12.5	R 56.25
Labour (Hours on site)	3.0	R 1,050.00

SubTotal : R 1,106.25

TOTAL : R 4,198.15

Findings

Water penetrated the electrical wiring when machine was cleaned. Extra care should be taken when cleaning the machine to prevent water damage.

Work Completed

Dried out the electrical box and replaced the wiring kit and fuse

Customer Signature