



Fig. 10. Thermal analysis. The melting process occurred about 200°C, indicating that the material was not well degraded to that point. Small amounts were melted, but they melted around the melting point, and they melted before the 200°C, which shows that the material was not degraded.