



EQUITY BANK LTD

PREVENTATIVE MAINTENANCE REPORT

17th July 2024

1. Site Details

Site: Buruburu Branch

Region: Nairobi

Contact: Evelyn Kamau - 0763752044

2. Equipment on Site

Equipment	Quantity	Serial Number	Tag Number	Status
10kVA Shield UPS	1	F01209001743	EQ322209	Okay

3. Job Description

Preventative maintenance of branch UPS.



4. Site Arrival Details





- The UPS was in normal mode and loads were connected.
- KPLC was available at 246V.

5. Troubleshooting and Action Points

- The UPS internal components were checked and no issues were noted.
- The unit's batteries were tested and are in good condition. The interconnecting cables were checked and are okay, and the connections are good.
- The UPS was tested in normal, bypass, and battery mode and the unit works well.
- The UPS was cleaned and serviced.
- Power loss was simulated and the unit provided the expected backup time.

6. Site Photos





7. Recommendations

- Schedule regular maintenance for optimum operation of the system