

# 3 phase primaries

## Strain insulator 3 Insulators

BRIG  
ELE  
Smart

Hot1

2-bolt Suspension clamp

5/8" bolt + curved washer + palnut

Pole

Hot2

Stirrup

Hot clamp

Hot3

Stranded aluminum overhead conductor

Down guy  
Guy wire

cut-outs

## 3 Fuses

Wye primary

Lightning arrester/ current limiting fuse

Primary bushing

Secondary terminals w internal breaker

Tank ground

Wye secondary

## 3 Transformers

Neutral to ground

Service neutral

Neutral to transformer

Neutral to ground  
compression  
coupling

Neutral

Shackle insulators

## Insulators

Insulated wire

## 3 secondary Hot drop wires

Ground wire #6 copper