




Unnamed tributary		ok-0407-r-001	Sedimentation Risk Index 48
<u>Common:</u> 8.3mi SW of Crestview <u>Drainage:</u> Turkey Gobbler Creek <u>GPS:</u> 30.646942, -86.616639 <u>Land owner:</u> US Government- Eglin AFB		<u>County:</u> Okaloosa <u>State:</u> Florida <u>PLSS(T-R-S):</u> 2N-24-19 <u>Parcel No.:</u> 1 <u>Road Name:</u> RR 215 Eglin AFB	
			
Crossing Structure- US		US	
Risk Factor	Ranking	Score	
US Channel Morph	C	5	
DS Channel Morph	C	5	
DS Bank Alteration	MINOR/PARTIAL	3	
Upstream Skew Angle	<5°	5	
Crossing fill condition	Good/Vegetated	5	
Inlet/Outlet Condition	No Impairment	5	
Road Approach Material	All Aggregate	5	
Potential Eroded Volume Mean	<21 y ³	5	
Approach Slope Mean	>4%	1	
Soil K Factor	<0.20	5	
Upstream Rt Outlet	Concrete	0	
Upstream Lt Outlet	Concrete	0	
Upstream Rt Ditch	Concrete	0	
Upstream Lt Ditch	Concrete	0	
Downstream Rt Outlet	Vegetated	1	
Downstream Lt Outlet	Concrete	0	
Downstream Rt Ditch	Bare soil	0	
Downstream Lt Ditch	Concrete	0	
Outlet Total	Partially Improved Outlet System	3	
Ditches Total	Unimproved Drainage System	1	
SRI Total	Low Risk	48	
Additional Site Features <u>Crossing Type and Quantity:</u> Culvert, 1 <u>Crossing Materials:</u> Reinforced Concrete <u>Soil Types:</u> 12,13,25 <u>Rt Approach Prism Fill:</u> 0.25in <u>Lt Approach Prism Fill:</u> 0.25in			
Feature	Within Range	Descriptive Field	
303(d)	No	N/A	
Wetland Species	Yes	1-3 FOCAL SPECIES IN UPLAND AREAS	
Rare and Imperiled	No	N/A	
Land Use/Cover	Yes	INSTITUTIONAL/ HARDWOOD CONIFEROUS-MIXED	
Candidate Mussels	No	N/A	
Sturgeon C.H.	No	N/A	

Notes: Both approaches paved hilltop to hilltop