



Yellow River		co-0819-001	Severity Score 1																																																																																
<u>Common:</u> 3.4mi SW of Horn Hill <u>Drainage:</u> Blackwater Bay <u>GPS:</u> 31.210386, -86.357481 <u>Land owner:</u> LB: Rayonier Woodlands LLC/ RB: T. Ivey Powell & Sons Inc		<u>County:</u> Covington <u>State:</u> Alabama <u>PLSS:</u> 3N-17E-21 <u>Parcel No.:</u> 4/3																																																																																	
																																																																																			
LB																																																																																			
<table border="1"> <thead> <tr> <th>Risk Factor</th> <th>Ranking</th> <th>Score</th> </tr> </thead> <tbody> <tr> <td>Channel Stability</td> <td>Good</td> <td>0.5</td> </tr> <tr> <td>Channel Alteration</td> <td>Historic, Mostly Recovered</td> <td>0</td> </tr> <tr> <td>Bank Erosion</td> <td>Historic</td> <td>0.5</td> </tr> <tr> <td>BEHI</td> <td>Low-Very Low</td> <td>0</td> </tr> <tr> <td>Local NPSP</td> <td>No Evidence</td> <td>0</td> </tr> <tr> <td>Shoring Structures</td> <td>Not Present</td> <td>0</td> </tr> <tr> <td>Pipe Discharge</td> <td>Not Present</td> <td>0</td> </tr> <tr> <td>Water Odors</td> <td>Not Present</td> <td>0</td> </tr> <tr> <td>Fish Passage Barrier</td> <td>Not Present</td> <td>0</td> </tr> <tr> <td>RB: Riparian Buffer</td> <td>100+ ft</td> <td>0</td> </tr> <tr> <td>LB: Riparian Buffer</td> <td>100+ ft</td> <td>0</td> </tr> <tr> <td>RB: Floodplain Access</td> <td>Full</td> <td>0</td> </tr> <tr> <td>LB: Floodplain Access</td> <td>Full</td> <td>0</td> </tr> <tr> <td>River Threat Index:</td> <td></td> <td>1</td> </tr> </tbody> </table>	Risk Factor	Ranking	Score	Channel Stability	Good	0.5	Channel Alteration	Historic, Mostly Recovered	0	Bank Erosion	Historic	0.5	BEHI	Low-Very Low	0	Local NPSP	No Evidence	0	Shoring Structures	Not Present	0	Pipe Discharge	Not Present	0	Water Odors	Not Present	0	Fish Passage Barrier	Not Present	0	RB: Riparian Buffer	100+ ft	0	LB: Riparian Buffer	100+ ft	0	RB: Floodplain Access	Full	0	LB: Floodplain Access	Full	0	River Threat Index:		1	<table border="1"> <thead> <tr> <th>Feature</th> <th>Within Range</th> <th>Descriptive Field</th> </tr> </thead> <tbody> <tr> <td>303(d)</td> <td>No</td> <td>N/A</td> </tr> <tr> <td>Wetland Species</td> <td>No</td> <td>N/A</td> </tr> <tr> <td>Rare and Imperiled</td> <td>No</td> <td>N/A</td> </tr> <tr> <td>Land Use/Cover</td> <td>Yes</td> <td>N/A / EAST GULF COASTAL PLAIN SMALL STREAM AND RIVER FLOODPLAIN FOREST</td> </tr> <tr> <td>Candidate Mussels</td> <td>Yes</td> <td>SOUTHERN SANDSHELL</td> </tr> <tr> <td>Sturgeon C.H.</td> <td>No</td> <td>N/A</td> </tr> <tr> <td colspan="3">Additional Site Features</td> </tr> <tr> <td colspan="2"><u>Stream Channel Woody Material:</u></td> <td>Moderate</td> </tr> <tr> <td colspan="2"><u>Impoundments:</u></td> <td>None</td> </tr> <tr> <td colspan="2"><u>Substrate Composition:</u></td> <td>Medium Sand</td> </tr> <tr> <td colspan="2"><u>Bank Material:</u></td> <td>Sand</td> </tr> </tbody> </table>		Feature	Within Range	Descriptive Field	303(d)	No	N/A	Wetland Species	No	N/A	Rare and Imperiled	No	N/A	Land Use/Cover	Yes	N/A / EAST GULF COASTAL PLAIN SMALL STREAM AND RIVER FLOODPLAIN FOREST	Candidate Mussels	Yes	SOUTHERN SANDSHELL	Sturgeon C.H.	No	N/A	Additional Site Features			<u>Stream Channel Woody Material:</u>		Moderate	<u>Impoundments:</u>		None	<u>Substrate Composition:</u>		Medium Sand	<u>Bank Material:</u>		Sand
Risk Factor	Ranking	Score																																																																																	
Channel Stability	Good	0.5																																																																																	
Channel Alteration	Historic, Mostly Recovered	0																																																																																	
Bank Erosion	Historic	0.5																																																																																	
BEHI	Low-Very Low	0																																																																																	
Local NPSP	No Evidence	0																																																																																	
Shoring Structures	Not Present	0																																																																																	
Pipe Discharge	Not Present	0																																																																																	
Water Odors	Not Present	0																																																																																	
Fish Passage Barrier	Not Present	0																																																																																	
RB: Riparian Buffer	100+ ft	0																																																																																	
LB: Riparian Buffer	100+ ft	0																																																																																	
RB: Floodplain Access	Full	0																																																																																	
LB: Floodplain Access	Full	0																																																																																	
River Threat Index:		1																																																																																	
Feature	Within Range	Descriptive Field																																																																																	
303(d)	No	N/A																																																																																	
Wetland Species	No	N/A																																																																																	
Rare and Imperiled	No	N/A																																																																																	
Land Use/Cover	Yes	N/A / EAST GULF COASTAL PLAIN SMALL STREAM AND RIVER FLOODPLAIN FOREST																																																																																	
Candidate Mussels	Yes	SOUTHERN SANDSHELL																																																																																	
Sturgeon C.H.	No	N/A																																																																																	
Additional Site Features																																																																																			
<u>Stream Channel Woody Material:</u>		Moderate																																																																																	
<u>Impoundments:</u>		None																																																																																	
<u>Substrate Composition:</u>		Medium Sand																																																																																	
<u>Bank Material:</u>		Sand																																																																																	

Notes: Some erosion, but may be a natural meander incision.