



Yellow River		co-0609-002	Severity Score 1																																																																																
<u>Common:</u> 1.3mi SW of Horn Hill <u>Drainage:</u> Blackwater Bay <u>GPS:</u> 31.0578726, -86.5108143 <u>Land owner:</u> LB: Nathaniel Wright, Tr. / RB: USA		<u>County:</u> Covington <u>State:</u> Alabama <u>PLSS:</u> 1N-15E-13 <u>Parcel No.:</u> 2/ 3																																																																																	
																																																																																			
LB																																																																																			
<table border="1"> <thead> <tr> <th>Risk Factor</th> <th>Ranking</th> <th>Score</th> </tr> </thead> <tbody> <tr><td>Channel Stability</td><td>Good</td><td>0.5</td></tr> <tr><td>Channel Alteration</td><td>None</td><td>0</td></tr> <tr><td>Bank Erosion</td><td>Historic</td><td>0.5</td></tr> <tr><td>BEHI</td><td>Low-Very Low</td><td>0</td></tr> <tr><td>Local NPSP</td><td>No Evidence</td><td>0</td></tr> <tr><td>Shoring Structures</td><td>Not Present</td><td>0</td></tr> <tr><td>Pipe Discharge</td><td>Not Present</td><td>0</td></tr> <tr><td>Water Odors</td><td>Not Present</td><td>0</td></tr> <tr><td>Fish Passage Barrier</td><td>Not Present</td><td>0</td></tr> <tr><td>RB: Riparian Buffer</td><td>100+ ft</td><td>0</td></tr> <tr><td>LB: Riparian Buffer</td><td>100+ ft</td><td>0</td></tr> <tr><td>RB: Floodplain Access</td><td>Full</td><td>0</td></tr> <tr><td>LB: Floodplain Access</td><td>Full</td><td>0</td></tr> <tr><td><b>River Threat Index:</b></td><td></td><td><b>1</b></td></tr> </tbody> </table>	Risk Factor	Ranking	Score	Channel Stability	Good	0.5	Channel Alteration	None	0	Bank Erosion	Historic	0.5	BEHI	Low-Very Low	0	Local NPSP	No Evidence	0	Shoring Structures	Not Present	0	Pipe Discharge	Not Present	0	Water Odors	Not Present	0	Fish Passage Barrier	Not Present	0	RB: Riparian Buffer	100+ ft	0	LB: Riparian Buffer	100+ ft	0	RB: Floodplain Access	Full	0	LB: Floodplain Access	Full	0	<b>River Threat Index:</b>		<b>1</b>	<table border="1"> <thead> <tr> <th>Feature</th> <th>Within Range</th> <th>Descriptive Field</th> </tr> </thead> <tbody> <tr><td>303(d)</td><td>Yes</td><td>METALS- MERCURY</td></tr> <tr><td>Wetland Species</td><td>No</td><td>N/A</td></tr> <tr><td>Rare and Imperiled</td><td>No</td><td>N/A</td></tr> <tr><td>Land Use/ Cover</td><td>No</td><td>N/A</td></tr> <tr><td>Candidate Mussels</td><td>No</td><td>N/A</td></tr> <tr><td>Sturgeon C.H.</td><td>Yes</td><td>N/A</td></tr> <tr> <td colspan="2"><b>Additional Site Features</b></td><td></td></tr> <tr> <td><u>Stream Channel Woody Material:</u></td><td></td><td>Infrequent</td></tr> <tr> <td><u>Impoundments:</u></td><td></td><td>None</td></tr> <tr> <td><u>Substrate Composition:</u></td><td></td><td>Medium Sand</td></tr> <tr> <td><u>Bank Material:</u></td><td></td><td>Sand and Roots</td></tr> </tbody> </table>		Feature	Within Range	Descriptive Field	303(d)	Yes	METALS- MERCURY	Wetland Species	No	N/A	Rare and Imperiled	No	N/A	Land Use/ Cover	No	N/A	Candidate Mussels	No	N/A	Sturgeon C.H.	Yes	N/A	<b>Additional Site Features</b>			<u>Stream Channel Woody Material:</u>		Infrequent	<u>Impoundments:</u>		None	<u>Substrate Composition:</u>		Medium Sand	<u>Bank Material:</u>		Sand and Roots
Risk Factor	Ranking	Score																																																																																	
Channel Stability	Good	0.5																																																																																	
Channel Alteration	None	0																																																																																	
Bank Erosion	Historic	0.5																																																																																	
BEHI	Low-Very Low	0																																																																																	
Local NPSP	No Evidence	0																																																																																	
Shoring Structures	Not Present	0																																																																																	
Pipe Discharge	Not Present	0																																																																																	
Water Odors	Not Present	0																																																																																	
Fish Passage Barrier	Not Present	0																																																																																	
RB: Riparian Buffer	100+ ft	0																																																																																	
LB: Riparian Buffer	100+ ft	0																																																																																	
RB: Floodplain Access	Full	0																																																																																	
LB: Floodplain Access	Full	0																																																																																	
<b>River Threat Index:</b>		<b>1</b>																																																																																	
Feature	Within Range	Descriptive Field																																																																																	
303(d)	Yes	METALS- MERCURY																																																																																	
Wetland Species	No	N/A																																																																																	
Rare and Imperiled	No	N/A																																																																																	
Land Use/ Cover	No	N/A																																																																																	
Candidate Mussels	No	N/A																																																																																	
Sturgeon C.H.	Yes	N/A																																																																																	
<b>Additional Site Features</b>																																																																																			
<u>Stream Channel Woody Material:</u>		Infrequent																																																																																	
<u>Impoundments:</u>		None																																																																																	
<u>Substrate Composition:</u>		Medium Sand																																																																																	
<u>Bank Material:</u>		Sand and Roots																																																																																	

Notes: New growth on bank degradation