



Shoal River			ok-0422-005		Severity Score 2	
<u>Common:</u> 4.5mi SE of Crestview <u>Drainage:</u> Yellow River <u>GPS:</u> 30.70517488, -86.533003383 <u>Land owner:</u> Haiseal Timber Co			<u>County:</u> Okaloosa <u>PLSS:</u> 2N-23W-3 <u>Parcel No.:</u> 1		<u>State:</u> Florida	
						
RB						
Risk Factor	Ranking	Score	Feature	Within Range	Descriptive Field	
Channel Stability	Poor	1.5	303(d)	No	N/A	
Channel Alteration	None	0	Wetland Species	Yes	1-3 FOCAL SPECIES IN UPLAND AREAS	
Bank Erosion	Not Eroding	0	Rare and Imperiled	Yes	GOLDSTRIPE DARTER, IRONCOLOR SHINER, SPECKLED CHUB	
BEHI	Moderate	0.5	Land Use/Cover	Yes	N/A / STREAMS AND WATERWAYS	
Local NPSP	No Evidence	0	Candidate Mussels	No	N/A	
Shoring Structures	Not Present	0	Sturgeon C.H.	No	N/A	
Pipe Discharge	Not Present	0	Additional Site Features <u>Stream Channel Woody Material:</u> Moderate <u>Impoundments:</u> None <u>Substrate Composition:</u> Medium Sand <u>Bank Material:</u> Sand and Leaf Litter			
Water Odors	Not Present	0				
Fish Passage Barrier	Not Present	0				
RB: Riparian Buffer	100+ ft	0				
LB: Riparian Buffer	100+ ft	0				
RB: Floodplain Access	Full	0				
LB: Floodplain Access	Full	0				
River Threat Index:		2				

Notes: Extremely shallow section of the river.

This sediment bar extents very far into the channel, leaving little room for the thalweg.