



Shoal River			ok-0422-007		Severity Score 5.5	
<u>Common:</u> 4.7mi SE of Crestview <u>Drainage:</u> Yellow River <u>GPS:</u> 30.695776786, -86.544244906 <u>Land owner:</u> RB: Haiseal Timber Co/ LB: Newman & Julie Bush			<u>County:</u> Okaloosa <u>PLSS(T-R-S):</u> 2N-23W-4 <u>Parcel No.:</u> 3/3.001		<u>State:</u> Florida	
						
LB						
Risk Factor	Ranking	Score	Feature	Within Range	Descriptive Field	
Channel Stability	Good	0.5	303d	No	N/A	
Channel Alteration	None	0	Wetland Species	Yes	1-3 FOCAL SPECIES IN WETLAND AREAS	
Bank Erosion	Historic	0.5	Rare and Imperiled	Yes	GOLDSTRIPE DARTER, SPECKLED CHUB IRONCOLOR SHINER	
BEHI	Moderate	0.5	Land Use/ Cover	Yes	AGRICULTURAL/ STREAMS AND WATERWAYS	
Local NPSP	Moderate Potential	1	Candidate Mussels	No	N/A	
Shoring Structures	Not Present	0	Sturgeon C.H.	No	N/A	
Pipe Discharge	Present	1.5	Additional Site Features <u>Stream Channel Woody Material:</u> Numerous <u>Impoundments:</u> None <u>Substrate Composition:</u> Medium Sand <u>Bank Material:</u> Sand and Roots			
Water Odors	Not Present	0				
Fish Passage Barrier	Not Present	0				
RB: Riparian Buffer	30-49 ft	0.5				
LB: Riparian Buffer	0-29 ft	0.75				
RB: Floodplain Access	Full	0				
LB: Floodplain Access	Partial	0.25				
River Threat Index:		5.5				

Notes: Pipe Discharge coming from a PVC pipe on the left bank upstream from this site.