



| Gum Creek | | | wa-1026-004 | | Severity Score 2.25 | |
|--|-----------------|--------------|---|---------------------|--|--|
| <u>Common:</u> 7.7mi NW of DeFuniak Springs <u>Drainage:</u> Shoal River <u>GPS:</u> 30.782837831, -86.22350037 <u>Land owner:</u> Victoria Arlene Trustee | | | <u>County:</u> Walton <u>PLSS:</u> 3N-20W-2/3 <u>Parcel No.:</u> 7; 1 | | <u>State:</u> Florida | |
|  | | |  | | | |
| US | | | | | | |
| Risk Factor | Ranking | Score | Feature | Within Range | Descriptive Field | |
| Channel Stability | Good | 0.5 | 303(d) | No | N/A | |
| Channel Alteration | None | 0 | Wetland Species | No | N/A | |
| Bank Erosion | Not Eroding | 0 | Rare and Imperiled | No | N/A | |
| BEHI | Low-Very Low | 0 | Land Use/Cover | Yes | AGRICULTURAL/ STREAMS AND WATERWAYS | |
| Local NPSP | Obvious Sources | 1.5 | Candidate Mussels | No | N/A | |
| Shoring Structures | Not Present | 0 | Sturgeon C.H. | No | N/A | |
| Pipe Discharge | Not Present | 0 | Additional Site Features <u>Stream Channel Woody Material:</u> Infrequent <u>Impoundments:</u> None <u>Substrate Composition:</u> Medium Sand <u>Bank Material:</u> Silt | | | |
| Water Odors | Not Present | 0 | | | | |
| Fish Passage Barrier | Not Present | 0 | | | | |
| RB: Riparian Buffer | 50-99 ft | 0.25 | | | | |
| LB: Riparian Buffer | 100+ ft | 0 | | | | |
| RB: Floodplain Access | Full | 0 | | | | |
| LB: Floodplain Access | Full | 0 | | | | |
| River Threat Index: | | 2.25 | | | | |

Notes: Old fence in stream and small creek on right bank.

Appears to be an access point for livestock, but there are none currently around.

Also an unpaved road on top of the left bank, as seen in the aerial.