



| Shoal River | | | ok-0423-008 | | Severity Score 2.5 | |
|--|----------------|--------------|---|---------------------|--|--|
| <u>Common:</u> 3.7mi SE of Crestview, .10mi Upstream of I-10 bridge <u>Drainage:</u> Yellow River <u>GPS:</u> 30.728122, -86.521925 <u>Land owner:</u> Haiseal Timber Co | | | <u>County:</u> Okaloosa <u>PLSS:</u> 3N-23W-26 <u>Parcel No.:</u> 9 | | <u>State:</u> Florida | |
|  | | |  | | | |
| RB | | | | | | |
| Risk Factor | Ranking | Score | Feature | Within Range | Descriptive Field | |
| Channel Stability | Poor | 1.5 | 303(d) | No | N/A | |
| Channel Alteration | None | 0 | Wetland Species | Yes | 1-3 FOCAL SPECIES IN UPLAND AREAS | |
| Bank Erosion | None | 0 | Rare and Imperiled | Yes | GOLDSTRIPE DARTER, IRONCOLOR SHINER, SPECKLED CHUB | |
| BEHI | High | 1 | Land Use/Cover | Yes | N/A / STREAMS AND WATERWAYS | |
| Local NPSP | No Evidence | 0 | Candidate Mussels | No | N/A | |
| Shoring Structures | Not Present | 0 | Sturgeon C.H. | No | N/A | |
| Pipe Discharge | Not Present | 0 | Additional Site Features <u>Stream Channel Woody Material:</u> Moderate <u>Impoundments:</u> None <u>Substrate Composition:</u> Medium Sand <u>Bank Material:</u> Sand | | | |
| Water Odors | Not Present | 0 | | | | |
| Fish Passage Barrier | Not Present | 0 | | | | |
| RB: Riparian Buffer | 100+ ft | 0 | | | | |
| LB: Riparian Buffer | 100+ ft | 0 | | | | |
| RB: Floodplain Access | Full | 0 | | | | |
| LB: Floodplain Access | Full | 0 | | | | |
| River Threat Index: | | 2.5 | | | | |

Notes: Aggradational site.