



Shoal River		ok-0615-007		Severity Score 4.75	
<u>Common:</u> 7.7mi NE of Crestview <u>Drainage:</u> Yellow River <u>GPS:</u> 30.791181735, -86.444845391 <u>Land owner:</u> Haiseal Timber Co		<u>County:</u> Okaloosa <u>PLSS(T-R-S):</u> 3N-22W-4 <u>Parcel No.:</u> 4		<u>State:</u> Florida	
					
RB					
Risk Factor	Ranking	Score	Feature	Within Range	Descriptive Field
Channel Stability	Fair	1	303d	No	N/A
Channel Alteration	None	0	Wetland Species	Yes	1-3 FOCAL SPECIES IN WETLAND AREAS
Bank Erosion	Active	1	Rare and Imperiled	Yes	GOLDSTRIPE DARTER, IRONCOLOR SHINER
BEHI	High	1	Land Use/ Cover	Yes	N/A/ STREAMS AND WATERWAYS
Local NPSP	No Evidence	0	Candidate Mussels	No	N/A
Shoring Structures	Not Present	0	Sturgeon C.H.	No	N/A
Pipe Discharge	Not Present	0			
Water Odors	Not Present	0			
Fish Passage Barrier	Not Present	0			
RB: Riparian Buffer	0-29 ft	0.75			
LB: Riparian Buffer	100+ ft	0			
RB: Floodplain Access	None	0.75			
LB: Floodplain Access	None	0.25			
River Threat Index:		4.75	Additional Site Features <u>Stream Channel Woody Material:</u> Moderate <u>Impoundments:</u> None <u>Substrate Composition:</u> Medium Sand <u>Bank Material:</u> Clay and Sand		

Notes: Natural meander erosion.