



Shoal River			ok-0615-011		Severity Score 3.5
<u>Common:</u> 5mi NE of Crestview <u>Drainage:</u> Yellow River <u>GPS:</u> 30.78738993, -86.490213592 <u>Land owner:</u> RB: Seagull Inc/ LB: Haiseal Timber Co			<u>County:</u> Okaloosa <u>State:</u> Florida <u>PLSS(T-R-S):</u> 3N-22W-6 <u>Parcel No.:</u> 6.001/6.001 A		
					
RB					
Risk Factor	Ranking	Score	Feature	Within Range	Descriptive Field
Channel Stability	Fair	1	303(d)	No	N/A
Channel Alteration	None	0	Wetland Species	Yes	1-3 FOCAL SPECIES IN UPLAND AREAS
Bank Erosion	Historic	0.5	Rare and Imperiled	Yes	GOLDSTRIPE DARTER, IRONCOLOR SHINER, SPECKLED CHUB
BEHI	Moderate	0.5	Land Use/ Cover	Yes	N/A / STREAMS AND WATERWAYS
Local NPSP	No Evidence	0	Candidate Mussels	No	N/A
Shoring Structures	Not Present	0	Sturgeon C.H.	No	N/A
Pipe Discharge	Not Present	0	Additional Site Features <u>Stream Channel Woody Material:</u> Moderate <u>Impoundments:</u> None <u>Substrate Composition:</u> Medium Sand <u>Bank Material:</u> Sand		
Water Odors	Not Present	0			
Fish Passage Barrier	Not Present	0			
RB: Riparian Buffer	0-29 ft	0.75			
LB: Riparian Buffer	100+ ft	0			
RB: Floodplain Access	None	0.75			
LB: Floodplain Access	Full	0			
River Threat Index:		3.5			

Notes: Lt Bank evidence of clear cutting. Rt bank aerals show a well defined historic meander pattern.