



Yellow River		co-0819-002	Severity Score 6																																																																				
<u>Common:</u> 8.8mi SW of Opp, Co Rd 32 bridge crossing <u>Drainage:</u> Blackwater Bay <u>GPS:</u> 31.190733, -86.360961 <u>Land owner:</u> Rayonier Woodlands		<u>County:</u> Covington <u>State:</u> Alabama <u>PLSS(T-R-S):</u> 3N-17E-33 <u>Parcel No.:</u> LLC 1/572AC																																																																					
																																																																							
RB																																																																							
<table border="1"> <thead> <tr> <th>Risk Factor</th> <th>Ranking</th> <th>Score</th> </tr> </thead> <tbody> <tr> <td>Channel Stability</td> <td>Good</td> <td>0.5</td> </tr> <tr> <td>Channel Alteration</td> <td>Historic, Mostly Recovered</td> <td>0.5</td> </tr> <tr> <td>Bank Erosion</td> <td>Not Eroding</td> <td>0</td> </tr> <tr> <td>BEHI</td> <td>Moderate</td> <td>0.5</td> </tr> <tr> <td>Local NPSP</td> <td>Obvious Sources</td> <td>1.5</td> </tr> <tr> <td>Shoring Structures</td> <td>Present</td> <td>1.5</td> </tr> <tr> <td>Pipe Discharge</td> <td>Not Present</td> <td>0</td> </tr> <tr> <td>Water Odors</td> <td>Not Present</td> <td>0</td> </tr> <tr> <td>Fish Passage Barrier</td> <td>Not Present</td> <td>0</td> </tr> <tr> <td>RB: Riparian Buffer</td> <td>0-29 ft</td> <td>0.75</td> </tr> <tr> <td>LB: Riparian Buffer</td> <td>0-29 ft</td> <td>0.75</td> </tr> <tr> <td>RB: Floodplain Access</td> <td>Full</td> <td>0</td> </tr> <tr> <td>LB: Floodplain Access</td> <td>Full</td> <td>0</td> </tr> <tr> <td colspan="2">River Threat Index:</td> <td>6</td> </tr> </tbody> </table>	Risk Factor	Ranking	Score	Channel Stability	Good	0.5	Channel Alteration	Historic, Mostly Recovered	0.5	Bank Erosion	Not Eroding	0	BEHI	Moderate	0.5	Local NPSP	Obvious Sources	1.5	Shoring Structures	Present	1.5	Pipe Discharge	Not Present	0	Water Odors	Not Present	0	Fish Passage Barrier	Not Present	0	RB: Riparian Buffer	0-29 ft	0.75	LB: Riparian Buffer	0-29 ft	0.75	RB: Floodplain Access	Full	0	LB: Floodplain Access	Full	0	River Threat Index:		6	<table border="1"> <thead> <tr> <th>Feature</th> <th>Within Range</th> <th>Descriptive Field</th> </tr> </thead> <tbody> <tr> <td>303(d)</td> <td>No</td> <td>N/A</td> </tr> <tr> <td>Wetland Species</td> <td>No</td> <td>N/A</td> </tr> <tr> <td>Rare and Imperiled</td> <td>No</td> <td>N/A</td> </tr> <tr> <td>Land Use/Cover</td> <td>Yes</td> <td>N/A / PASTURE/HAY</td> </tr> <tr> <td>Candidate Mussels</td> <td>No</td> <td>N/A</td> </tr> <tr> <td>Sturgeon C.H.</td> <td>No</td> <td>N/A</td> </tr> <tr> <td colspan="3"> Additional Site Features <u>Stream Channel Woody Material:</u> Infrequent <u>Impoundments:</u> None <u>Substrate Composition:</u> Medium Sand <u>Bank Material:</u> Sand </td> </tr> </tbody> </table>		Feature	Within Range	Descriptive Field	303(d)	No	N/A	Wetland Species	No	N/A	Rare and Imperiled	No	N/A	Land Use/Cover	Yes	N/A / PASTURE/HAY	Candidate Mussels	No	N/A	Sturgeon C.H.	No	N/A	Additional Site Features <u>Stream Channel Woody Material:</u> Infrequent <u>Impoundments:</u> None <u>Substrate Composition:</u> Medium Sand <u>Bank Material:</u> Sand		
Risk Factor	Ranking	Score																																																																					
Channel Stability	Good	0.5																																																																					
Channel Alteration	Historic, Mostly Recovered	0.5																																																																					
Bank Erosion	Not Eroding	0																																																																					
BEHI	Moderate	0.5																																																																					
Local NPSP	Obvious Sources	1.5																																																																					
Shoring Structures	Present	1.5																																																																					
Pipe Discharge	Not Present	0																																																																					
Water Odors	Not Present	0																																																																					
Fish Passage Barrier	Not Present	0																																																																					
RB: Riparian Buffer	0-29 ft	0.75																																																																					
LB: Riparian Buffer	0-29 ft	0.75																																																																					
RB: Floodplain Access	Full	0																																																																					
LB: Floodplain Access	Full	0																																																																					
River Threat Index:		6																																																																					
Feature	Within Range	Descriptive Field																																																																					
303(d)	No	N/A																																																																					
Wetland Species	No	N/A																																																																					
Rare and Imperiled	No	N/A																																																																					
Land Use/Cover	Yes	N/A / PASTURE/HAY																																																																					
Candidate Mussels	No	N/A																																																																					
Sturgeon C.H.	No	N/A																																																																					
Additional Site Features <u>Stream Channel Woody Material:</u> Infrequent <u>Impoundments:</u> None <u>Substrate Composition:</u> Medium Sand <u>Bank Material:</u> Sand																																																																							

Notes: Bridge crossing and campsite. Rip rap and concrete used as shoring structure.