



Shoal River		ok-0615-001		Severity Score 7.5	
<u>Common:</u> 9.1mi NW of Crestview, CR 393 Bridge Crossing <u>Drainage:</u> Shoal River <u>GPS:</u> 30.79108517, -86.42064962 <u>Land owner:</u> Donald Cunard		<u>County:</u> Okaloosa <u>PLSS(T-R-S):</u> 3N-22W-2 <u>Parcel No.:</u> 6		<u>State:</u> Florida	
					
LB					
<b>Risk Factor</b>	<b>Ranking</b>	<b>Score</b>	<b>Feature</b>	<b>Within Range</b>	<b>Descriptive Field</b>
Channel Stability	Fair	1	303(d)	No	N/A
Channel Alteration	In Recovery	1	Wetland Species	No	N/A
Bank Erosion	Active	1	Rare and Imperiled	Yes	GOLDSTRIPE DARTER, SPECKLED CHUB, IRONCOLOR SHINER
BEHI	Moderate	0.5	Land Use/Cover	Yes	N/A / STREAMS AND WATERWAYS
Local NPSP	Obvious Sources	1.5	Candidate Mussels	Yes	SOUTHERN SANDSHELL
Shoring Structures	Present	1.5	Sturgeon C.H.	No	N/A
Pipe Discharge	Not Present	0	<b>Additional Site Features</b>		
Water Odors	Not Present	0	<u>Stream Channel Woody Material:</u> Infrequent		
Fish Passage Barrier	Not Present	0	<u>Impoundments:</u> None		
RB: Riparian Buffer	100+ ft	0	<u>Substrate Composition:</u> Clay Marl		
LB: Riparian Buffer	0-29 ft	0.75	<u>Bank Material:</u> Sand and Clay		
RB: Floodplain Access	Partial	0.25			
LB: Floodplain Access	Full	0			
<b>River Threat Index:</b>		<b>7.5</b>			

Notes: Rip rap used as shoring structure underneath CR 393 bridge. Power line crossing, bridge, and anthropomorphic evidence at this site. House boat being stored/lived in under bridge.