



Five Runs Creek			co-0924-003		Severity Score 4.5	
<u>Common:</u> 9mi S of Carolina, .08mi US of Co Rd 24 bridge crossing <u>Drainage:</u> Yellow River <u>GPS:</u> 31.10748248, -86.518107393 <u>Land owner:</u> USA- Conecuh Nat. Forest			<u>County:</u> Covington <u>PLSS(T-R-S):</u> 2N-15E-26 <u>Parcel No.:</u> 1		<u>State:</u> Alabama	
						
RB						
<b>Risk Factor</b>	<b>Ranking</b>	<b>Score</b>	<b>Feature</b>	<b>Within Range</b>	<b>Descriptive Field</b>	
Channel Stability	Good	0.5	303(d)	No	N/A	
Channel Alteration	Historic, Mostly Recovered	0.5	Wetland Species	No	N/A	
Bank Erosion	Not Eroding	0	Rare and Imperiled	No	N/A	
BEHI	High	1	Land Use/Cover	Yes	N/A/ EAST GULF COASTAL PLAIN SOUTHERN MESIC SLOPE FOREST, UPLAND LONGLEAF PINE WOODLAND - OPEN UNDERSTORY MODI	
Local NPSP	No Evidence	0	Candidate Mussels	Yes	CHOCTAW BEAN	
Shoring Structures	Present	1.5	Sturgeon C.H.	No	N/A	
Pipe Discharge	Not Present	0	<b>Additional Site Features</b>			
Water Odors	Not Present	0	<u>Stream Channel Woody Material:</u> Infrequent			
Fish Passage Barrier	Not Present	0	<u>Impoundments:</u> None			
RB: Riparian Buffer	0-29 ft	0.75	<u>Substrate Composition:</u> Medium Sand			
LB: Riparian Buffer	100+ ft	0	<u>Bank Material:</u> Sand and Manmade Materials			
RB: Floodplain Access	Partial	0.25				
LB: Floodplain Access	Full	0				
<b>River Threat Index:</b>		<b>4.5</b>				

Notes: Shoring structure is concrete and wood for an old bridge crossing wall.