



Yellow River			ok-0225-005		Severity Score 8	
<u>Common:</u> 12.4mi SW of Crestview, .42 mi DS of Tarwick Creek <u>Drainage:</u> Yellow River <u>GPS:</u> 30.672143, -86.751921 <u>Land owner:</u> RB: Roland & Sara Henson/ LB: USA			<u>County:</u> Okaloosa <u>State:</u> Florida <u>PLSS(T-R-S):</u> 16-2N-25 <u>Parcel No.:</u> RB: 4.034a / LB: 2			
						
RB						
Risk Factor	Ranking	Score	Feature	Within Range	Descriptive Field	
Channel Stability	Good	0.5	303(d)	No	N/A	
Channel Alteration	None	0	Wetland Species	Yes	1-3 FOCAL SPECIES IN UPLAND AREAS	
Bank Erosion	Historic	0.5	Rare and Imperiled	Yes	ALBAMA SHAD, ALLIGATOR GAR, BLUE NOSE SHINER, GULF STURGEON, SPECKLED CHUB, IRONCOLOR SHINER, SPOTTED BULLHEAD, SPECKLED DARTER	
BEHI	High	1	Land Use/Cover	Yes	N/A/ STREAMS AND WATERWAYS	
Local NPSP	Obvious Sources	1.5	Candidate Mussels	No	N/A	
Shoring Structures	Present	1.5	Sturgeon C.H.	Yes	N/A	
Pipe Discharge	Present	1.5	Additional Site Features			
Water Odors	Not Present	0	<u>Stream Channel Woody Material:</u> Infrequent			
Fish Passage Barrier	Not Present	0	<u>Impoundments:</u> None			
RB: Riparian Buffer	0-29 ft	0.75	<u>Substrate Composition:</u> Sand			
LB: Riparian Buffer	100+ ft	0	<u>Bank Material:</u> Sand			
RB: Floodplain Access	None	0.75				
LB: Floodplain Access	Full	0				
River Threat Index:		8				

Notes: Pipe discharge coming from a small PVC pipe on right bank boat launch. Approx. 100 yards of brick and concrete shoring structure present. "Easy Street" leads to house on right bank.