



Turkey Creek			wa-1028-001		Severity Score 4.75	
<u>Common:</u> 7mi N of Mossy Head <u>Drainage:</u> Shoal River <u>GPS:</u> 30.849801722, -86.25527761 <u>Land owner:</u> Martha Pridgen			<u>County:</u> Walton <u>PLSS(T-R-S):</u> 4N-20W-16 <u>Parcel No.:</u> 4		<u>State:</u> Florida	
						
RB						
Risk Factor	Ranking	Score	Feature	Within Range	Descriptive Field	
Channel Stability	Fair	1	303(d)	Yes	COLIFORMS, TURBIDITY	
Channel Alteration	None	0	Wetland Species	No	N/A	
Bank Erosion	Active	1	Rare and Imperiled	No	N/A	
BEHI	High	1	Land Use/Cover	Yes	AGRICULTURAL/ STREAMS AND WATERWAYS	
Local NPSP	No Evidence	0	Candidate Mussels	No	N/A	
Shoring Structures	Not Present	0	Sturgeon C.H.	No	N/A	
Pipe Discharge	Not Present	0	Additional Site Features <u>Stream Channel Woody Material:</u> Infrequent <u>Impoundments:</u> None <u>Substrate Composition:</u> Clay Marl <u>Bank Material:</u> Clay			
Water Odors	Not Present	0				
Fish Passage Barrier	Not Present	0				
RB: Riparian Buffer	0-29 ft	0.75				
LB: Riparian Buffer	100 + ft	0				
RB: Floodplain Access	None	0.75				
LB: Floodplain Access	Partial	0.25				
River Threat Index:		4.75				

Notes: Power line crossing. Very low sinuosity.