



Shoal River			ok-0423-007		Severity Score 3.25
<u>Common:</u> 3.6mi SE of Crestview <u>Drainage:</u> Yellow River <u>GPS:</u> 30.732367, -86.520503 <u>Land owner:</u> Haiseal Timber Co			<u>County:</u> Okaloosa <u>State:</u> Florida <u>PLSS(T-R-S):</u> 3N-23W-26 <u>Parcel No.:</u> 9		
					
RB					
Risk Factor	Ranking	Score	Feature	Within Range	Descriptive Field
Channel Stability	Poor	1.5	303(d)	No	N/A
Channel Alteration	None	0	Wetland Species	Yes	1-3 FOCAL SPECIES IN UPLAND AREAS
Bank Erosion	Not eroding	0	Rare and Imperiled	Yes	GOLDSTRIPE DARTER, IRONCOLOR SHINER, SPECKLED CHUB
BEHI	High	1	Land Use/Cover	Yes	N/A / STREAMS AND WATERWAYS
Local NPSP	No Evidence	0	Candidate Mussels	No	N/A
Shoring Structures	Not Present	0	Sturgeon C.H.	No	N/A
Pipe Discharge	Not Present	0			
Water Odors	Not Present	0			
Fish Passage Barrier	Not Present	0			
RB: Riparian Buffer	0-29 ft	0.75			
LB: Riparian Buffer	100+ ft	0			
RB: Floodplain Access	Full	0			
LB: Floodplain Access	Full	0			
River Threat Index:		3.25	<b>Additional Site Features</b> <u>Stream Channel Woody Material:</u> Moderate <u>Impoundments:</u> None <u>Substrate Composition:</u> Medium Sand <u>Bank Material:</u> Sand		

Notes: Aggradational site.