



Yellow River		co-0805-005	Severity Score 3.75																																																																																	
<u>Common:</u> 16mi S of Andalusia <u>Drainage:</u> Blackwater Bay <u>GPS:</u> 31.0770612, -86.488424621 <u>Land owner:</u> RB: USA / LB: James & Patricia Battles		<u>County:</u> Covington <u>State:</u> Alabama <u>PLSS(T-R-S):</u> 1N-16E-6 <u>Parcel No.:</u> RB: 2/339AC / LB:1/272AC																																																																																		
																																																																																				
RB																																																																																				
<table border="1"> <thead> <tr> <th>Risk Factor</th> <th>Ranking</th> <th>Score</th> </tr> </thead> <tbody> <tr><td>Channel Stability</td><td>Fair</td><td>1</td></tr> <tr><td>Channel Alteration</td><td>None</td><td>0</td></tr> <tr><td>Bank Erosion</td><td>Active</td><td>1</td></tr> <tr><td>BEHI</td><td>High</td><td>1</td></tr> <tr><td>Local NPSP</td><td>No Evidence</td><td>0</td></tr> <tr><td>Shoring Structures</td><td>Not Present</td><td>0</td></tr> <tr><td>Pipe Discharge</td><td>Not Present</td><td>0</td></tr> <tr><td>Water Odors</td><td>Not Present</td><td>0</td></tr> <tr><td>Fish Passage Barrier</td><td>Not Present</td><td>0</td></tr> <tr><td>RB: Riparian Buffer</td><td>100+ ft</td><td>0</td></tr> <tr><td>LB: Riparian Buffer</td><td>30-49 ft</td><td>0.5</td></tr> <tr><td>RB: Floodplain Access</td><td>Full</td><td>0</td></tr> <tr><td>LB: Floodplain Access</td><td>Partial</td><td>0.25</td></tr> <tr><td>River Threat Index:</td><td></td><td>3.75</td></tr> </tbody> </table>	Risk Factor	Ranking	Score	Channel Stability	Fair	1	Channel Alteration	None	0	Bank Erosion	Active	1	BEHI	High	1	Local NPSP	No Evidence	0	Shoring Structures	Not Present	0	Pipe Discharge	Not Present	0	Water Odors	Not Present	0	Fish Passage Barrier	Not Present	0	RB: Riparian Buffer	100+ ft	0	LB: Riparian Buffer	30-49 ft	0.5	RB: Floodplain Access	Full	0	LB: Floodplain Access	Partial	0.25	River Threat Index:		3.75	<table border="1"> <thead> <tr> <th>Feature</th> <th>Within Range</th> <th>Descriptive Field</th> </tr> </thead> <tbody> <tr><td>303(d)</td><td>Yes</td><td>METALS- MERCURY</td></tr> <tr><td>Wetland Species</td><td>No</td><td>N/A</td></tr> <tr><td>Rare and Imperiled</td><td>No</td><td>N/A</td></tr> <tr><td>Land Use/ Cover</td><td>Yes</td><td>N/A / SUCCESSIONAL SHRUB/SCRUB (CLEAR CUT)</td></tr> <tr><td>Candidate Mussels</td><td>No</td><td>N/A</td></tr> <tr><td>Sturgeon C.H.</td><td>Yes</td><td>N/A</td></tr> <tr><td colspan="3">Additional Site Features</td></tr> <tr><td colspan="2"><u>Stream Channel Woody Material:</u></td><td>None</td></tr> <tr><td colspan="2"><u>Impoundments:</u></td><td>None</td></tr> <tr><td colspan="2"><u>Substrate Composition:</u></td><td>Medium Sand</td></tr> <tr><td colspan="2"><u>Bank Material:</u></td><td>Sand</td></tr> </tbody> </table>			Feature	Within Range	Descriptive Field	303(d)	Yes	METALS- MERCURY	Wetland Species	No	N/A	Rare and Imperiled	No	N/A	Land Use/ Cover	Yes	N/A / SUCCESSIONAL SHRUB/SCRUB (CLEAR CUT)	Candidate Mussels	No	N/A	Sturgeon C.H.	Yes	N/A	Additional Site Features			<u>Stream Channel Woody Material:</u>		None	<u>Impoundments:</u>		None	<u>Substrate Composition:</u>		Medium Sand	<u>Bank Material:</u>		Sand
Risk Factor	Ranking	Score																																																																																		
Channel Stability	Fair	1																																																																																		
Channel Alteration	None	0																																																																																		
Bank Erosion	Active	1																																																																																		
BEHI	High	1																																																																																		
Local NPSP	No Evidence	0																																																																																		
Shoring Structures	Not Present	0																																																																																		
Pipe Discharge	Not Present	0																																																																																		
Water Odors	Not Present	0																																																																																		
Fish Passage Barrier	Not Present	0																																																																																		
RB: Riparian Buffer	100+ ft	0																																																																																		
LB: Riparian Buffer	30-49 ft	0.5																																																																																		
RB: Floodplain Access	Full	0																																																																																		
LB: Floodplain Access	Partial	0.25																																																																																		
River Threat Index:		3.75																																																																																		
Feature	Within Range	Descriptive Field																																																																																		
303(d)	Yes	METALS- MERCURY																																																																																		
Wetland Species	No	N/A																																																																																		
Rare and Imperiled	No	N/A																																																																																		
Land Use/ Cover	Yes	N/A / SUCCESSIONAL SHRUB/SCRUB (CLEAR CUT)																																																																																		
Candidate Mussels	No	N/A																																																																																		
Sturgeon C.H.	Yes	N/A																																																																																		
Additional Site Features																																																																																				
<u>Stream Channel Woody Material:</u>		None																																																																																		
<u>Impoundments:</u>		None																																																																																		
<u>Substrate Composition:</u>		Medium Sand																																																																																		
<u>Bank Material:</u>		Sand																																																																																		

Notes: Lack of vegetation on left bank could lead to further active erosion.