


STEP 1



STEP 2

Limit/Estop Switch Setting In Mach3

Engine Configuration... Ports & Pins

Encoder/MFG's

Spindle Setup

Mill Options

Port Setup and Axis Selection

Motor Outputs

Input Signals

Output Signals

Signal	Enabled	Port #	Pin Number	Active Low	Emulated	HotKey
X ++		1	12			0
X --		1	12			0
X Home		1	12			0
Y ++		1	11			0
Y --		1	11			0
Y Home		1	11			0
Z ++ 文本		1	10			0
Z --		1	10			0
Z Home		1	10			0
A ++		1	0			0
A --		1	0			0
A Home		1	0			0
B ++		1	0			0
B --		1	0			0
B Home		1	0			0
C ++		1	0			0
C --		1	0			0
C Home		1	0			0
Input #1		1	0			0
Input #2		1	0			0
Input #3		1	0			0
Input #4		1	0			0
Probe		1	0			0
Index		1	0			0
Limit Ovrd		1	0			0
Limit Ovrd		1	0			0
EStop		1	13			0

Pins 10-13 and 15 are inputs. Only these 5 pin numbers may be

Automated Setup of Inputs

确定

取消

应用(A)