

⑥ Paint drying

- When conducting high temperature forced drying, be sure that the temperature of painted surface does not exceed 80°C.
 - Drying temperature over 80°C may deform rubber and plastic parts, and result in separation of adhesive-bonded joints.
- If the drying temperature inevitably exceeds 80°C, follow the instructions below.
 - Remove components or protect them from high temperature with heat insulation sheet, blanket, etc.
 - Remove all the control units.
- When performing forced drying, remove the following parts.
 - Mirrors
 - Air intake duct
 - Fender rubber
 - Wiper
 - Washer nozzle
 - Head lamp
 - Decal(Exchange for new one)
 - Emblem(Exchange for new one)
- For the scratches that can be made during unfastening and fastening screws, bolts, or nuts, touch them up with a brush soaked in clear lacquer, etc.