

# Inspection Report

**Truck Serial Number:** 1

**Truck Model:** 23

**Inspection ID:** 1

**Inspector:** User

**Inspection Employee ID:** 30

**Inspection Date & Time:** 2024-08-09 22:12

**Location of Inspection:** vellore

**Service Meter Hours:** 50

**Customer/Company Name:** VIT

**CAT Customer ID:** 123

## Tire Information

**Pressure on the left front tire:** yes

**Pressure for the right front tire:** good

**Condition of the left front tire:** good

**Condition of the right front tire:** replacement

**Pressure on the left rear tire:** stable

**Pressure on the right rear tire:** good

**Condition of the left rear tire:** change

**Condition of the right rear tire:** good

**Overview of tire conditions and pressures:** right front tire and left rear tire must be replaced



## Battery Information

**Battery brand:** CAT

**Last replaced:** last year

**Current voltage:** 12V

**Water level in the battery:** good

**Visible damage:** no

**Signs of leakage or rust:** no

**Summary of battery condition:** battery is in perfect condition



## Exterior Information

**Rust, dents, or damage:** no

**Oil leak in the suspension area:** no

**Summary of exterior condition:** everything is fine



## Brakes Information

**Brake fluid level:** good

**Condition of the front brakes:** good

**Condition of the rear brakes:** good

**Status of the emergency brake:** good

**Summary of brake condition:** brakes are in perfect condition



## Engine Information

**Rust, dent, or damage in the engine area:** no

**Condition of the engine oil:** good

**Color of the engine oil:** brown

**Condition of the brake fluid:** good

**Color of the brake fluid:** clean

**Oil leak in the engine:** no

**Summary of engine condition:** good



## Voice of Customer

**Comments or feedback from the customer:** no

**Specific feedback from the customer:** tires need to be replaced

**Particular issues mentioned by the customer:** tires



## Summary

The inspection reveals that the tires need to be replaced, but the battery, exterior, brakes, and engine are in good condition. Customer feedback highlights the tire issue as a primary concern.