



Manual Z lift
Pull belt left

Probe sensor
port


Tool length
sensor



Set X=0 Set Y=0 Set Z=0



Probe Z=0




Go to tool change position Probe tool length

EXTRA OFFSET
(During run)

Enable offsets Lift Z +100 mm

X Y Z



MANUAL MOVE / JOG
(Program stopped)


Jog speed
10 100 1000 2000 mm/min

0.01 0.1 1 10 mm/step

X Y Z A


+

-



FEEDRATE OVERRIDE

Press to zero



SPINDLE OVERRIDE



3D PROBE ACTIVATE →