



From Port Index

1

Sweep Freq (FDOC)

Use for x-axis

SWPVAR.SWP1

Plot all traces

Use for x-axis

Plot all traces

Select with tuner

Disable sweep

RL = 25

RL = 50

RL = 100

on the sweep if select with tuner it will tune for only the sweep setup.