



Fire side  
plasterboard  
(Pb1) fall off.  
Excessive  
thermal bowing