

Excessive
contraction in
LVDT



Excessive
bowing on
ambient side
plasterboard
(Pb4)