



Excessive thermal bowing and visible flame from burner

Discolouration of ambient side plasterboard (Pb4)