

A photograph showing a blue metal edge stud, likely part of a vehicle's body or a heavy-duty frame. The stud is bent and shows signs of local crushing, particularly at the corner where it meets another section. A red dashed circle is drawn around the damaged area. The background is a light-colored, possibly concrete or metal, surface with some debris.

Local
crushing
in edge
stud