

# VEX CLAW ARM ASSEMBLY SKETCHES

Concern 1: ~~the~~ vertical height issues caused by motor:  
flip motor sideways.

