

First: Turn DC-HV off and then
Click Configure Hardware to begin

Configure Moller Hardware

Beam Polarization (%)

Backout Moller Hardware

0.00000

Change Helmholtz Polarity

Beam Polarization Error

Negative

Positive

0.00000

Reset EPICS DAQ

EPICS DAQ status

enabled

Target

Done

LEFT

RIGHT

EMPTY

Helmholtz Magnet

NEG

POS

OFF



Suggested Current

Current ReadBack

Upstream Quad



2486

-1.954

Downstream Quad



2258

-1.954

LEFT PMT HV



-1426

Volts

RIGHT PMT HV



-1285

Volts

L,R Trues

0

L,R accidentals

0