

Lab t2

Schematic Errors:

- The board header “FTDI-TTL232-3V3” does not have a connection to MCLR at the FTDI pin 6 named “RTS#”. To remedy this error, solder one wire between pin 6 of the FTDI-TTL232-3V3 and pin 1 named “MCLR#” of the “SV1” header.