

**HAZARDOUS AREA MONITORING FOR
INDUSTRIAL PLANTS POWERED BY IOT**

PROJECT DEVELOPMENT PHASE

SPRINT-1

SUBMITTED BY

SAPNA U K	(113219041099)
GOLI HEMASWI	(113219041031)
KAVITHA S	(113219041049)
PRIYADARSHINI S	(113219041090)

**BACHELOR OF ENGINEERING IN ELECTRONICS
AND COMMUNICATION ENGINEERING**

CODE:

```
int sensor = A0;
#include<LiquidCrystal.h>
LiquidCrystal lcd(12, 11, 5, 4, 3, 2);
//int sensor = A0; // Assigning analog pin A1 to variable 'sensor'
float tempc; //variable to store temperature in degree Celsius
float vout; //temporary variable to hold sensor reading
void setup()
{
  pinMode(sensor,INPUT); // Configuring pin A1 as input
  Serial.begin(9600);
  lcd.begin(16,2);
  delay(500);
}
void loop()
{
  vout=analogRead(A0);
  float prehum=(vout/5);
  vout=(vout*5.00)/1024.0;
  tempc=(vout-0.5)*100; // Storing value in Degree Celsius
  float humconst = (0.16/0.0062);
  float humi = prehum - humconst;
  float pretruehumconst = 0.00216*tempc;
```

```
float pretruehum = 1.0546 - pretruehumconst;
float truehum = humi/pretruehum;
//delay(1000);
lcd.setCursor(0,0);
lcd.print("Degree C = ");
lcd.print(tempc);
lcd.setCursor(0,1);
lcd.print("Humidity%= ");
lcd.print(truehum);
delay(1000); //Delay of 1 second for ease of viewing in serial monitor
}
```

OUTPUT:

