






CODION LTD		TITLE A3000_16MB	
SIZE A3	DIMENSIONS	VARIANT [No Variations]	REVISION 1.0
DATE 2023		SHEET 1 OF 5	
FILE A3000_16MB_Glue.SchDoc		DRAWN BY	







MRST is fed back down the plug for ARM. IC47 on the motherboard must have pin12 lifted so it is not driving this signal. The lifted leg should be wired to the RST_IN connector on our board instead.

Pullups for motherboard RAM may not be required as BANK pulls OE, but undriven circuits "probably bad" so fit if paranoic

CODION LTD		TITLE A3000_16MB	
SIZE A3	DIMENSIONS	VARIANT [No Variations]	REVISION 1.0
DATE 2023		SHEET 2 OF 5	
FILE A3000_16MB.SchDoc		DRAWN BY	



CODION LTD		TITLE A3000_16MB	
SIZE A3	DIMENSIONS	VARIANT [No Variations]	REVISION 1.0
DATE 2023		SHEET 3 OF 5	
FILE A3000_16MB_M2.SchDoc		DRAWN BY	



CODION LTD		TITLE A3000_16MB	
SIZE A3	DIMENSIONS	VARIANT [No Variations]	REVISION 1.0
DATE 2023		SHEET 5 OF 5	
FILE A3000_16MB_M4.SchDoc		DRAWN BY	