

# GreenAuto - Vehicle Damage & Repair Cost Report

## Damage Details

Detected Damage Type: bumper\_scratch

Estimated Repair Cost: Rs.9188.17

## Recommended Repair Shops

Shop Name	Distance (km)	City
Perera Wheel Alignment Service	2.72	Malabe
Wasantha Motors	2.88	Malabe
Not Specified	3.70	Not Specified

GreenAuto is your trusted AI-powered vehicle damage assessment and repair cost estimation platform. We help drivers and insurance providers make informed decisions with accurate, real-time analysis. Find the best repair services near you and explore eco-friendly vehicle solutions to reduce your carbon footprint.

For support, visit our website: [www.greenauto.com](http://www.greenauto.com) | Email: [support@greenauto.com](mailto:support@greenauto.com) | Hotline: +94 76 123 4567