

# MDU Cabling.

No	Activity	Hazard	Person(s) in Danger	Control Measures	Residual Risk Rating
64	MDU Cabling	<b>Asbestos / ACMs</b>  <b>Slips, trips and falls</b>  <b>Services - power, gas and water.</b>  <b>Working at height</b>  <b>Electric shock</b>  <b>Concealed cables</b>	Employees  Contractors  Customer	<ul style="list-style-type: none"> <li>• Request asbestos survey. Inspect work area for ACM's and stop work if identified.</li> <li>• Keep cables in a safe location and guard and protect where required. Maintain good housekeeping. Inspect work area and request removal of any item likely to cause trips or ensure items are secured.</li> <li>• Visual inspection for concealed services or obstructions. Discuss potential hazards with customer and check walls before drilling or inserting fixings.</li> <li>• Always maintain 3 points of contact when working on ladders. Utilise Tetra Level 2 or equivalent. Only use company provided equipment. Do not lean from ladders.</li> <li>• MEWP operators to be trained and competent in use (IPAF).</li> <li>• Harness to be worn and secured at all times when in MEWP basket.</li> <li>• Use battery operated power tools.</li> <li>• Ensure all tools and equipment are securely stored.</li> <li>• Wear task specific PPE</li> </ul>	Low