

BuildSafe Risk Assessment Report

Infrastructure: Sydney High-Rise Office (BUILDING)

Location: -33.865, 151.209

Final Risk Score: 58%

Compliance Contribution (NaN%): 65%

Weather Impact (20%): 0%

Weather Conditions:

- Temperature: 27.15°C
- Wind Speed: 7.44 m/s
- Precipitation: 0 mm/h
- Conditions: Clouds

Compliance Violations:

- Building exceeds height limit (50m) [MEDIUM]
- Insufficient number of exits [HIGH]