



4.0
Clean
Condition

2+ Smart Keys

Modified

Detailed Condition Report

Modified: Suspension Modified

Front Bumper: Paint Damage (Lower driver side corner (Lower driver side corner)

Driver Fender: Substandard Paint Repair (Near headlight housing

Passenger Outer bed: Scratches : (Upper rear section Below window)

Tire Report

Front Left	Front Right	Rear Left	Rear Left
6/32"	7/32"	6/32"	7/32"
Overall Status:	Overall Fracture	Overall Status:	Overall Healthy

Describe your image



Thinking

