


RECORD OF INSPECTION

Part No. : 1F67700-1		Rev. : N/A		W.I. No. ATP1F67700-1		Rev. : B		Date : 10-10-16			
Unit Name : OCU								Dept. : 650			
Product No. : C00187						Job/Ser. No. : 0034					
Lot No. : —			Operation No. : —			Area Covered : ATP Vibration					
Submission	Lot Size	Sample					Accept/ Reject Stamp	Inspected			
		Size	Rejects	Defects	Operator No.	Normalizing No.		By	Date		
First	1	1	NA	NA	NA	NA		S.B.	10-13-16		
Second											
Third											
Defects : Describe part and/or area involved. Indicate Serial No. if more than one.							Defects		Disp. Action Code	Rework By	Insp. By
							Qty.	Code			
<p>During the Z-axis vibe, a spike was present in the control signal. The spike was at 20Hz, was 0.24dB below the lower tolerance and was less than 3Hz in width. This spike meets the allowances stated in the ATP paragraph 3.2.5.3.4.</p> <p>CY 10-10-16</p> <p>Carlos [Signature] 10-13-2016</p>											