








< Shunt Sensing >

Title		<Title>	
Size	Document Number	Rev	
B	<Doc>	<RevCode>	
Date:	Thursday, August 27, 2015	Sheet	1 of 5


Decoupling Cap
각 pin 근처에 하나씩 배치




< SPI >




< RESET >




< JTAG >




< DAC >






< 20 MHz OSC >









< easyDSP >




File	<Title>	Rev	<V1.1>
Size	Document Number		
Date	Monday, August 24, 2015	Sheet	2 of 5




Relay 16A



Title		
<Title>		
Size	Document Number	Rev
B	<Doc>	<RevCode>
Date:	Monday, August 24, 2015	Sheet 4 of 5



< 15 V Fault >



12/18 V Fault -> 1.96/2.94 V

Title <Title>			
Size B	Document Number <Doc>		Rev <Rev Code>
Date:	Friday, August 21, 2015	Sheet 5 of 5	

Rev	<RevCode:
-----	-----------