



# WIRING DIAGRAMS 3PH MOTORS

## THREE-PHASE MOTORS SINGLE POLARITY 6 TERMINALS TA – TC SERIES

Delta Connection  $\Delta$  (Low Voltage)




Star Connection Y (High Voltage)




## THREE-PHASE MOTORS DOUBLE POLARITY SINGLE WINDING (DAHLANDER CONNECTION) 6 TERMINALS MSD – TCD SERIES

Delta Connection  $\Delta$  – Low Speed




Double Star Connection YY – High



## THREE-PHASE MOTORS DOUBLE POLARITY DOUBLE WINDING 6 TERMINALS MSD – TCD SERIES

Star Connection Y – Low Speed



Star Connection Y – High Speed

