

# ACTION ALERT

PART # 60-13011-C

CONCERN Diameter of flat on underside of hex is undersize.

New tool is needed before next production run.

Contact Steve Reckamp before setting up job.

Name: *Steve Reckamp*

Date: 1/4/2016