

" Quality Alert "

ID #:

2017 QA-010

Part #:


RM292P-N

Problem Description:

Burr in cross hole that is causing low flow at customer

Containment Action:

De--burr all on hand inventory. Make sure to visually inspect parts for defect



Department Mgr: Ken McGuire

Quality Engineer: Matthew King

Quality Director: Dave Besancenez

Team Fact. Signature: Andy Weston, Dave Edging

Removal Date: N/A

Distribution : Job packet, work cell

VERIFICATION OF TRAINING LOG

Topic: _____

Date: _____ Time: _____ Training Hours: _____

Facilitator's : _____

I certify that I have received, and understand the training topic listed above.

Attendees:

Employee's *Printed* Name

Employee's Signature

1 _____
2 _____
3 _____
4 _____
5 _____
6 _____
7 _____
8 _____
9 _____
10 _____
11 _____
12 _____
13 _____
14 _____
15 _____
16 _____
17 _____
18 _____
19 _____
20 _____
21 _____
22 _____

1 _____
2 _____
3 _____
4 _____
5 _____
6 _____
7 _____
8 _____
9 _____
10 _____
11 _____
12 _____
13 _____
14 _____
15 _____
16 _____
17 _____
18 _____
19 _____
20 _____
21 _____
22 _____