

# " Quality Alert "

**ID #:** 2017 QA-005

**Part #:** FS12

**Problem Description:**

Flow arrow is pointing in the wrong direction.

**Containment Action:**

Parts need to be visually inspected when being made for correct arrow direction

**BAD**

**GOOD**



**Department Mgr:** Ken McGuire

**Quality Engineer:** Matthew King

**Quality Director:** Dave Besancenez

**Team Fact. Signature:** Andy Weston

**Removal Date:**

**Distribution :** Hydromats, Master file

## VERIFICATION OF TRAINING LOG

Topic: \_\_\_\_\_

Date: \_\_\_\_\_ Time: \_\_\_\_\_ Training Hours: \_\_\_\_\_

Facilitator's : \_\_\_\_\_

I certify that I have received, and understand the training topic listed above.

### Attendees:

Employee's *Printed* Name

Employee's Signature

1 \_\_\_\_\_  
2 \_\_\_\_\_  
3 \_\_\_\_\_  
4 \_\_\_\_\_  
5 \_\_\_\_\_  
6 \_\_\_\_\_  
7 \_\_\_\_\_  
8 \_\_\_\_\_  
9 \_\_\_\_\_  
10 \_\_\_\_\_  
11 \_\_\_\_\_  
12 \_\_\_\_\_  
13 \_\_\_\_\_  
14 \_\_\_\_\_  
15 \_\_\_\_\_  
16 \_\_\_\_\_  
17 \_\_\_\_\_  
18 \_\_\_\_\_  
19 \_\_\_\_\_  
20 \_\_\_\_\_  
21 \_\_\_\_\_  
22 \_\_\_\_\_

1 \_\_\_\_\_  
2 \_\_\_\_\_  
3 \_\_\_\_\_  
4 \_\_\_\_\_  
5 \_\_\_\_\_  
6 \_\_\_\_\_  
7 \_\_\_\_\_  
8 \_\_\_\_\_  
9 \_\_\_\_\_  
10 \_\_\_\_\_  
11 \_\_\_\_\_  
12 \_\_\_\_\_  
13 \_\_\_\_\_  
14 \_\_\_\_\_  
15 \_\_\_\_\_  
16 \_\_\_\_\_  
17 \_\_\_\_\_  
18 \_\_\_\_\_  
19 \_\_\_\_\_  
20 \_\_\_\_\_  
21 \_\_\_\_\_  
22 \_\_\_\_\_